

# V1910-CMW520-R1513P50 Release Notes

© Copyright 2013 Hewlett-Packard Development Company, L.P. The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

The information in this document is subject to change without notice.



# Contents

Version information	1
Version number	1
Version history	1
Hardware and software compatibility matrix	2
Upgrading restrictions and guidelines	4
Hardware feature updates	4
V1910-CMW520-R1513P50	4
V1910-CMW520-R1513P15	4
V1910-CMW520-R1513P13	5
V1910-CMW520-R1513P07	5
V1910-CMW520-R1513P06	5
V1910-CMW520-R1513P05	5
V1910-CMW520-R1513P01	5
V1910-CMW520-R1513	5
V1910-CMW520-R1512P10	5
V1910-CMW520-R1512P05	5
V1910-CMW520-R1511	5
V1910-CMW520-F1510	5
V1910-CMW520-R1112	6
V1910-CMW520-R1111P02	6
V1910-CMW520-R1111P01	6
V1910-CMW520-R1111	6
V1910-CMW520-R1109	6
V1910-CMW520-R1108P01	6
V1910-CMW520-R1108	6
Software feature and command updates	6
MIB updates	6
Operation changes	8
Operation changes in CMW-R1513P50	8
Operation changes in CMW-R1513P15	8
Operation changes in CMW-R1513P13	8
Operation changes in CMW-R1513P07	8
Operation changes in CMW-R1513P06	9
Operation changes in CMW-R1513P05	9
Operation changes in CMW-R1513P01	9
Operation changes in CMW-R1513	9
Operation changes in CMW-R1512P10	9
Operation changes in CMW-R1512P05	9
Operation changes in CMW-R1511	9
Operation changes in CMW-F1510	9
Operation changes in CMW-R1112	10
Operation changes in CMW-R1111P02	10
Operation changes in CMW-R1111P01	10
Operation changes in CMW-R1111	10
Operation changes in CMW-R1109	10
Operation changes in CMW-R1108P01	10
Operation changes in CMW-R1108	10

Restrictions and cautions .....	10
Open problems and workarounds.....	11
List of resolved problems .....	12
Resolved problems in CMW520-R1513P50 .....	12
Resolved problems in CMW520-R1513P15 .....	13
Resolved problems in CMW520-R1513P13 .....	13
Resolved problems in CMW520-R1513P07 .....	14
Resolved problems in CMW520-R1513P06 .....	15
Resolved problems in CMW520-R1513P05 .....	16
Resolved problems in CMW520-R1513P01 .....	16
Resolved problems in CMW520-R1513 .....	16
Resolved problems in CMW520-R1512P10 .....	17
Resolved problems in CMW520-R1512P05 .....	17
Resolved problems in CMW520-R1511 .....	17
Resolved problems in CMW520-F1510 .....	17
Resolved problems in CMW520-R1112 .....	18
Resolved problems in CMW520-R1111P02 .....	19
Resolved problems in CMW520-R1111P01 .....	19
Resolved problems in CMW520-R1111 .....	19
Resolved problems in CMW520-R1109 .....	20
Resolved problems in CMW520-R1108P01 .....	21
Resolved problems in CMW520-R1108 .....	21
Related documentation .....	21
Documentation set .....	21
Obtaining documentation .....	22
Contacting HP .....	22
Subscription service .....	22
Appendix A Feature list .....	23
Hardware features .....	23
Software features .....	24
Appendix B Upgrading software .....	27
Upgrading software from Boot ROM menus .....	27
Accessing the basic Boot menu .....	29
Accessing the extended Boot menu .....	30
Loading Software Using XMODEM through Console Port .....	32
Loading Software Using TFTP through Ethernet Port .....	41
Loading Software Using FTP through Ethernet Port .....	44
Upgrading at the CLI .....	46
Loading Software Using TFTP .....	46

# List of Tables

Table 1 Version history .....	1
Table 2 HP 1910 product family matrix .....	2
Table 3 Hardware and software compatibility matrix.....	3
Table 4 MIB updates .....	6
Table 5 1910 series hardware features.....	23
Table 6 Software features of the V1910 series .....	24
Table 7 Approaches to loading software on the switch .....	27
Table 8 Shortcut keys .....	28
Table 9 Basic Boot ROM menu options.....	29
Table 10 BASIC-ASSISTANT menu options.....	30
Table 11 Extended Boot ROM menu options .....	31
Table 12 EXTEND-ASSISTANT menu options.....	32
Table 13 Description of the TFTP parameters.....	42
Table 14 Description of the FTP parameters .....	44

This document describes the features, restrictions and guidelines, open problems, and workarounds for version V1910-CMW520-R1513P50. Before you use this version in a live network, back up the configuration and test the version to avoid software upgrade affecting your live network.

Use this document in conjunction with V1910-CMW520-R1513P50 Release Notes (Software Feature Changes) and the documents listed in "[Related documentation.](#)"

## Version information

### Version number

Comware software, Version 5.20, Release 1513P50

**Note:** You can see the version number with the command **summary** in any view. Please see **Note**①.

### Version history

**Table 1** Version history

Version number	Last version	Release date	Release type	Remarks
V1910-CMW520-R1513P50	V1910-CMW520-R1513P15	2013-05-23	Release version	Fixes bugs.
V1910-CMW520-R1513P15	V1910-CMW520-R1513P13	2013-03-21	Release version	Fixes bugs.
V1910-CMW520-R1513P13	V1910-CMW520-R1513P07	2013-02-25	Release version	Modified feature: Upgrading the PoE software from the CLI Fixes bugs.
V1910-CMW520-R1513P07	V1910-CMW520-R1513P06	2013-01-05	Release version	Fixes bugs.
V1910-CMW520-R1513P06	V1910-CMW520-R1513P05	2012-11-29	Release version	Fixes bugs.
V1910-CMW520-R1513P05	V1910-CMW520-R1513P01	2012-10-30	Release version	Fixes bugs.
V1910-CMW520-R1513P01	V1910-CMW520-R1513	2012-10-19	Release version	Fixes bugs.
V1910-CMW520-R1513	V1910-CMW520-R1512P10	2012-09-20	Release version	New feature: Automatic configuration file backup for software downgrading, Configuring IPv6 Modified feature: Configuring a local user, Setting the super password, Creating users Fixes bugs.

Version number	Last version	Release date	Release type	Remarks
V1910-CMW520-R15 12P10	V1910-CMW520-R1 512P05	2012-08-24	Release version	Fixes bugs.
V1910-CMW520-R15 12P05	V1910-CMW520-R1 511	2012-07-12	Release version	Fixes bugs.
V1910-CMW520-R15 11	V1910-CMW520-F15 10	2012-5-25	Release version	Fixes bugs. adds features
V1910-CMW520-F15 10	V1910-CMW520-R1 112	2012-5-14	Feature version	Fixes bugs. adds features
V1910-CMW520-R11 12	V1910-CMW520-R1 111P01	2012-4-11	Release version	Fixes bugs.
V1910-CMW520-R11 11P02	V1910-CMW520-R1 111P01	2012-6-19	Release version	Fixes bugs.
V1910-CMW520-R11 11P01	V1910-CMW520-R1 111	2012-3-20	Release version	Fixes bugs.
V1910-CMW520-R11 11	V1910-CMW520-R1 109	2012-1-4	Release version	Fixes bugs.
V1910-CMW520-R11 09	V1910-CMW520-R1 108P01	2011-9-26	Release version	Fixes bugs. adds features
V1910-CMW520-R11 08P01	V1910-CMW520-R1 108	2011-8-17	Release version	Fixes bugs.
V1910-CMW520-R11 08	None	2011-5-13	Release version	Fixes bugs.

## Hardware and software compatibility matrix

**Please note that prior to October 2011, these products were shipped under the 3Com Baseline Plus 2900 series brand. The table below shows the mapping between the 3Com 2900 models and HP 1910 switches. Please note that the products are identical except for the branding. HP recommends that customers upgrade to the latest version of software to avail of the new software branding.**

**Table 2 HP 1910 product family matrix**

HP 1910	3Com 2900
1910-16G : JE005A	3Com Baseline Plus Switch 2920
1910-24G : JE006A	3Com Baseline Plus Switch 2928
1910-24G-PoE (365W) : JE007A	3Com Baseline Plus Switch 2928 HPWR
1910-24G-PoE (170W) : JE008A	3Com Baseline Plus Switch 2928 PWR
1910-48G : JE009A	3Com Baseline Plus Switch 2952
1910-8G : JG348A	---
1910-8G-PoE+ (65W) : JG349A	---
1910-8G-PoE+ (180W) : JG350A	---

**CAUTION:**

To avoid an upgrade failure, use [Table 4](#) to verify the hardware and software compatibility before performing an upgrade.

**Table 3 Hardware and software compatibility matrix**

Item	Specifications
Product family	HP 1910 Switch series
Hardware platform	HP1910-16G : JE005A HP 1910-24G : JE006A HP 1910-24G-PoE (365W) : JE007A HP 1910-24G-PoE (170W) : JE008A HP 1910-48G : JE009A HP 1910-8G : JG348A HP 1910-8G-PoE+ (65W) : JG349A HP 1910-8G-PoE+ (180W) : JG350A
Memory	128 MB
Flash	128 MB
Boot ROM version	Version 161 (Note: Perform the <b>summary</b> command in any view to view the version information. See Note② )
Host software	V1910-CMW520-R1513P50.bin
iMC version	iMC PLAT 5.2 (E0401P05) iMC UAM 5.2 (E0402P05) iMC EAD 5.2 (E0402P05) iMC QoS 5.2 (E0401) iMC BIMS 5.2 (E0401L03) iMC TAM 5.2 (E0401) iMC SHM 5.2 (E0401)
iNode version	iNode PC 5.2 (E0408)
Remarks	None

```
<HP V1910 Switch>summary
```

```
Select menu option:          Summary
IP Method:                  Manual
IP address:                  192.168.1.22
Subnet mask:                 255.255.255.0
Default gateway:
```

```
Current boot app is: flash:/V1910-CMW520-R1513P50.bin
```

```
Next main boot app is: flash:/v1910-cmw520-R1511.bin
```

```
Next backup boot app is: NULL
```

HP Comware Platform Software  
Comware Software, Version 5.20 Release 1513P50, ----- Note①  
Copyright (c) 2004-2012 Hewlett-Packard Development Company, L.P.  
HP V1910-48G Switch uptime is 0 week, 0 day, 0 hour, 33 minutes

HP V1910-48G Switch  
128M bytes DRAM  
128M bytes Nand Flash Memory  
Config Register points to Nand Flash

Hardware Version is REV.B  
CPLD Version is 002  
Bootrom Version is 161 ----- Note②  
[SubSlot 0] 48GE+4SFP Hardware Version is REV.B

## Upgrading restrictions and guidelines

- A new password encryption algorithm is adopted since Release F1510. If you roll back the software from a version between F1510 and F1513P01 (not included) to a version lower than F1510, the password that has been processed by the new encryption algorithm cannot be restored, and user login may fail.
- If the configuration is saved on a switch where a software version of R1513 or higher is running but the software version in the startup configuration file is still lower than F1510 (not included), the switch first backs up the startup configuration file and then saves the running configuration to the startup configuration file. For example, suppose the startup configuration file is **a.cfg**. The switch first backs up **a.cfg** as **\_a\_bak.cfg**, and then saves the running configuration to **a.cfg**.
- After an upgrade from an old version to a version between R1109 and F1513P01, the system.xml configuration becomes invalid.
- After an upgrade from a version between R1109 and R1513P01 to R1513P05 or later, the system.xml configuration file is preferred by the system.
- After a downgrade from R1513P05 or later to R1108P01 or before, you must reconfigure idle timeout, syslog buffer, ntp server1, and ntp server2 in the web interface.

## Hardware feature updates

### V1910-CMW520-R1513P50

None

### V1910-CMW520-R1513P15

None



V1910-CMW520-R1513P13

None

V1910-CMW520-R1513P07

None

V1910-CMW520-R1513P06

None

V1910-CMW520-R1513P05

None

V1910-CMW520-R1513P01

None

V1910-CMW520-R1513

None

V1910-CMW520-R1512P10

None

V1910-CMW520-R1512P05

None

V1910-CMW520-R1511

None

V1910-CMW520-F1510

Support new devices 1910-8G , 1910-8G-PoE+ (65W) and 1910-8G-PoE+ (180W)

V1910-CMW520-R1112

None

V1910-CMW520-R1111P02

None

V1910-CMW520-R1111P01

None

V1910-CMW520-R1111

None

V1910-CMW520-R1109

None

V1910-CMW520-R1108P01

None

V1910-CMW520-R1108

None

## Software feature and command updates

For more information about the software feature and command update history, see V1910-CMW520-R1513P50 Release Notes (Software Feature Changes).

## MIB updates

Table 4 MIB updates

Item	MIB file	Module	Description
<b>V1910-CMW520-R1513P50</b>			
New	None	None	None
Modified	None	None	None

<b>Item</b>	<b>MIB file</b>	<b>Module</b>	<b>Description</b>
<b>V1910-CMW520-R1513P15</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1513P13</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1513P07</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1513P06</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1513P05</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1513P01</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1513</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1512P10</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1512P05</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1511</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-F1510</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1112</b>			
New	None	None	None
Modified	None	None	None

Item	MIB file	Module	Description
<b>V1910-CMW520-R1111P02</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1111P01</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1111</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1109</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1108P01</b>			
New	None	None	None
Modified	None	None	None
<b>V1910-CMW520-R1108</b>			
New	None	None	None
Modified	None	None	None

## Operation changes

### Operation changes in CMW-R1513P50

None

### Operation changes in CMW-R1513P15

None

### Operation changes in CMW-R1513P13

None

### Operation changes in CMW-R1513P07

None

## Operation changes in CMW-R1513P06

None

## Operation changes in CMW-R1513P05

- Changed the default state of all TCP/UDP ports from "enabled" to "disabled", including TCP port 7547, and UDP port 161.

## Operation changes in CMW-R1513P01

- Modified the value of node hh3cUserPassword in HH3C-USER-MIB due to security concerns. When read, hh3cUserPassword always returns a zero-length OCTET STRING.

## Operation changes in CMW-R1513

- Added a function of enabling or disabling IPv6 on the **Network > IPv6 Management > IPv6 Service** Web page for the 1910.
- If the configuration is saved on a switch where a software version of R1513 or higher is running but the software version in the startup configuration file is still lower than F1510 (not included), the switch first backs up the startup configuration file and then saves the running configuration to the startup configuration file. For example, suppose the startup configuration file is **a.cfg**. The switch first backs up **a.cfg** as **\_a\_bak.cfg**, and then saves the running configuration to **a.cfg**.

## Operation changes in CMW-R1512P10

None

## Operation changes in CMW-R1512P05

None

## Operation changes in CMW-R1511

None

## Operation changes in CMW-F1510

None

## Operation changes in CMW-R1112

None

## Operation changes in CMW-R1111P02

None

## Operation changes in CMW-R1111P01

After you downgrade a 1910 switch from Release R1111P01 or above to an earlier version than Release R1111P01, its SysOid changes to identify the switch as a 3COM 2900 device, but the change does not affect the use of the switch. For the HP 1910 and 3Com 2900 switch mapping, see "HP 1910 product family matrix."

## Operation changes in CMW-R1111

None

## Operation changes in CMW-R1109

1. Merge the ".xml" configuration into the ".cfg" configuration.
2. The Key can be auto-generated for the SSH service on the **Web->Network->Service** page.
3. The PKI certificate can be auto-generated for HTTPS service on the **Web->Network->Service** page.

## Operation changes in CMW-R1108P01

None

## Operation changes in CMW-R1108

None

## Restrictions and cautions


1. Do not power off the switch during a write operation, such as a save operation.
2. Displaying MAC addresses on a port does not show multicast MAC addresses.
3. Performing VCT check on an up port cannot detect the cable length.

- The LED for a Gigabit SFP port blinks when the port is receiving packets, and is steady on when the port is sending packets.

## Open problems and workarounds

### LSD44945

- Symptom: In the following network diagram, a ping operation from the PC to 1910\_1 experiences a 30-second interruption.
- Condition: This symptom might occur when the following conditions exist:
  - All 1910 switches and the PC are in the same subnet.
  - MSTP is configured to avoid loops and all 1910 switches belong to MSTP instance 0.
  - The port G1/0/49 of the root bridge 1910\_2 is shut down.



- Workaround: Configure the **stp no-agreement-check** command on the root ports.

### LSD070866

- Symptom: After the configuration file that contains the login password is saved and then the software is downgraded from the new version to a version earlier than F1510, a login attempt using the correct password fails.
- Condition: In this version of code, the password encryption within configuration files has been enhanced and cannot be interpreted by earlier revisions of the agent code. This means that if a unit is downgraded to earlier code, it may no longer be possible to login and manage the device.
- Workarounds:
  - Before upgrading to the new code, it is necessary to ensure password control is disabled. Execute the *"undo password-control enable"* and then save this configuration file as a backup in case you need to downgrade the software again. If it is later necessary to downgrade to earlier software, force the switch to use this backup configuration file by executing a *"startup saved-configuration (filename)"* command before rebooting to the old code. Then, after the code has been downgraded, the device can be logged in from the console or by Telnet, but not SSH. The SSH authentication details will need to be reset.

- If no backup configuration has been saved but it is still possible to access the device management via some method while running the old code (e.g. Console, Telnet or SSH), then you can redefine all the device management passwords as required.
- If after a downgrade it is impossible to login to the device via any method, then there are two ways to recover the switch:
  - From the BOOT menu, set the new code to run again and reboot the device. Disable Telnet authentication:
 

```
User-interface vty 0 4
Authentication mode none
```

 Then save the configuration and downgrade the code again, login via Telnet and reset all the passwords as required.
    - From the BOOT menu. On boot-up, use Ctrl+B to enter the Boot menu and then force the unit to use the factory default configuration (bypassing the user configuration). The unit will then need to be fully reconfigured.

### LSD071592

- Symptom: When a GE copper port is connected to a device that uses a RealTek RTL8169 network chip, the port goes up and down twice, and then goes up.
- Condition: This symptom might occur when a GE copper port is connected to a device that uses a RealTek RTL8169 network chip.
- Workaround: None.

### LSD074352

- Symptom: A PC fails to acquire an IPv6 address through DHCP.
- Condition: This symptom occurs if the switch port connected to the PC is configured with selective QinQ.
- Workaround: None.

## List of resolved problems

### Resolved problems in CMW520-R1513P50

#### LSD075026

- Symptom: Using the IE10 browser to access the Web interface of the switch fails.
- Condition: This symptom occurs because the Web interface does not support IE10.

#### LSD075114

- Symptom: After a cable that connects a PoE port to a Sony DV is removed and inserted, the DV does not work.
- Condition: This symptom occurs after a cable that connects a PoE port to a Sony DV is removed and inserted.

#### LSD074731

- Symptom: Failed to upload files to an appointed path when authentication is required by iMC BIMs.



- Condition: When system try to upload a file to iMC BIMs and authentication is required.

## Resolved problems in CMW520-R1513P15

### LSD074632

- Symptom: Global IPv6 ACLs (either manually configured or automatically assigned by a protocol) do not take effect. For example, IPv6 ACLs assigned by portal do not take effect.
- Condition: This symptom exists in R1513P13.

### LSD074433

- Symptom: The memory resources are used up if many SSH connections are established using the Nessus software.
- Condition: This symptom occurs if many SSH connections are established using the Nessus software.

### LSD074398

- Symptom: If the VLAN IDs specified for selective QinQ to match are not continuous (for example, **aw-vlan-id inbound 2 to 33 44 to 100**), selective QinQ can only tag an outer VLAN ID for frames from the first VLAN ID range (2 to 33 in this example).
- Condition: This symptom occurs if the VLAN IDs specified for selective QinQ to match are not contiguous.

## Resolved problems in CMW520-R1513P13

### LSD074352

- Symptom: A PC fails to acquire an IPv6 address through DHCP.
- Condition: This symptom occurs if the switch port connected to the PC is configured with selective QinQ.

### LSD074356

- Symptom: A terminal that has not passed portal authentication on the connected switch can use software such as TFTP and QQ to access the network.
- Condition: This symptom can be seen when the switch is enabled with portal authentication.

### LSD73898

- Symptom: The switch does not learn MAC addresses.
- Condition: This symptom might occur when the following conditions exist:
  - CPU usage is high.
  - The MAC address table is full.
  - MAC addresses are added and deleted continually.
  - STP flapping occurs on the neighbor devices.

### LSD74078

- Symptom: The service type displayed in the Web interface is different from the one configured at the CLI on the switch.

- Condition: This symptom can be seen when **service-type** has been configured in the **local-user** command.

#### LSD74087

- Symptom: When the idle timeout timer of a user that has logged in to the Web interface expires, an incorrect prompt "Error: Failed to set the new password!" appears.
- Condition: This symptom can be seen when the idle timeout timer of a user that has logged in to the Web interface expires.

#### LSD74065

- Symptom: A security-audit user cannot use the IPv6 ping and traceroute functions in the Web interface.
- Condition: This symptom occurs when a security-audit user tries to use the IPv6 ping and traceroute functions in the Web interface.

#### LSD074153

- Symptom: When a Web management user clicks the **Creating diagnostic information file** button in the Web interface, the switch abnormally reboots.
- Condition: This symptom occurs when a Web management user clicks the **Creating diagnostic information file** button in the Web interface.

#### LSD074123

- Symptom: The switch fails to upgrade the PoE firmware.
- Condition: This symptom occurs during a PoE firmware upgrade.

## Resolved problems in CMW520-R1513P07

#### LSD073500

- Symptom: When a PC connected to a 1910 switch uses the same IP address as the connected VLAN interface, the switch does not prompt address conflict.
- Condition: This symptom can be seen when a PC connected to a 1910 switch uses the same IP address as the connected VLAN interface.

#### LSD073797

- Symptom: After a looped port detected by loopback-detection in multi-port mode has its loop source moved to another port, the port still cannot forward or receive packets.
- Condition: This symptom can be seen after a looped port detected by loopback-detection in multi-port mode has its loop source moved to another port.

#### LSD073921

- Symptom: Users' STACK function cannot be used.
- Condition: This symptom occurs because NTDP&NDP is disabled on the switch by default.

#### LSD073860

- Symptom: Walking the ifOutErrors MIB node on a port always returns 0.
- Condition: This symptom might be seen when the port has incorrect packet statistics.

#### LSD073706

- Symptom: Disabling a port in the Web interface results in a reboot of the switch.

- Condition: This symptom might occur when you disable a port in the Web interface.

#### LSD073081

- Symptom: An error occurs when a user accesses the **Device -> File Management** page.
- Condition: This symptom can be seen if the user has logged in to the Web interface by using a domain name with more than 19 characters

## Resolved problems in CMW520-R1513P06

#### LSD073546

- Symptom: A terminal that matches the SNMP ACL cannot access the switch.
- Condition: This symptom occurs when a terminal that resides in the subnet permitted by the SNMP ACL tries to access the switch.

#### LSD073193

- Symptom: An SNMP walk on ifInErrors MIB returns a value of 0 when the interface has statistics about error packets.
- Condition: This symptom occurs when the interface has statistics about error packets.

#### LSD073066

- Symptom: The NTP Web page displays garbage characters.
- Condition: This symptom might occur if you modify and save NTP settings when the switch runs a version between R1109 and R1513P05, and then upgrade the software to R1513P05.

#### LSD073063

- Symptom: The NTP Web page displays wrong information.
- Condition: This symptom might occur if you configure two authentication-keyids and then modify the first configured authentication-keyid.

#### LSD073364

- Symptom: The NDP & NTDP information displayed using the Firefox browser has font and format problems.
- Condition: This symptom occurs when you use the Firefox browser to display the NDP & NTDP information of the switch.

#### LSD073358

- Symptom: Prompt information displayed during LACP Web configuration has format problems.
- Condition: This symptom exists in the prompt information displayed during LACP Web configuration.

#### LSD072680

- Symptom: An STP Discarding port can still learn MAC addresses.
- Condition: This symptom occurs on an STP Discarding port.

#### HWD039649

- Symptom: When an unsupported 100M fiber module is inserted, the console does not print "not supported by hardware."
- Condition: This symptom occurs when an unsupported 100M fiber module is inserted.

## HWD039650

- Symptom: The switch cannot identify 10G fiber modules. When a 10G module is inserted, the console does not print "not supported by hardware."
- Condition: This symptom occurs when a 10G module is inserted.

## Resolved problems in CMW520-R1513P05

### LSD072881

- Symptom: Using the super password to switch a user privilege level fails.
- Condition: This symptom occurs if the super password is configured in irreversible mode through Web.

### LSD073016

- Symptom: A string of more than four characters cannot be correctly entered into the Contact or Location box in the SNMP setup web page.
- Condition: This symptom occurs if you enter a string of more than four characters into the Contact or Location box in the SNMP setup web page.

### LSD072938

- Symptom: An 802.1X-enabled port broadcasts received EAPOL-Start packets.
- Condition: This symptom might occur if 802.1X is enabled globally and on the port, and an 802.1X user has passed 802.1X authentication on the port.

### LSD072681

- Symptom: After the software is upgraded to R1109 or higher, the settings configured in the old version on the web idle timeout, syslog buffer, ntp server1, ntp server2 Web pages do not take effect.
- Condition: This symptom occurs if all or parts of these settings have been configured before the software is upgraded to R1109 or higher.

## Resolved problems in CMW520-R1513P01

### LSD073073

- Symptom: When access the hh3cUserPassword node of hh3cUserInfoTable by SNMP, the device returns the user's password.
- Condition: Access the hh3cUserPassword node of hh3cUserInfoTable by SNMP.

## Resolved problems in CMW520-R1513

### LSD072305

- Symptom: IPv6 cannot be enabled in the Web interface after the software is upgraded from a version lower than F1510 to F1510 or higher.
- Condition: This symptom occurs after the software is upgraded from a version lower than F1510 to F1510 or higher.

### LSD071416

- Symptom: Some Web pages for 1910, such as ACL IPv6, IPv6 router, and IPv6 ping/traceroute pages, do not provide online help information.
- Condition: This problem exists on some Web pages for 1910.

## Resolved problems in CMW520-R1512P10

### LSD072006

- Symptom: The IPv6 does not work.
- Condition: This symptom might occur after the switch is upgraded from a version earlier than F1510 to F1510 or later.

### LSD070321

- Symptom: The switch runs out of memory when the configuration file is restored on the **Device > Configuration** Web page.
- Condition: This symptom might occur if a configuration file that is close to or exceeds the free Flash memory is restored on the **Device > Configuration** Web page.

### LSD072080

- Symptom: The switch is vulnerable to HTTP session Hijack attacks.
- Condition: This symptom might be seen when HTTP session Hijack attacks exist.

## Resolved problems in CMW520-R1512P05

### LSD071395

- Symptom: When a GE copper port is connected to a device that uses the RTL8169 network chip of RealTek, the port repeatedly goes up and down.
- Condition: This symptom might occur when a GE copper port is connected to a device that uses the RTL8169 network chip of RealTek.

## Resolved problems in CMW520-R1511

None

## Resolved problems in CMW520-F1510

### ZDD05100

- Symptom: The switch updates ARP entries for only 32 MAC addresses when a large number of MAC addresses are moved to different ports.
- Condition: This symptom might occur when a large number of MAC addresses are moved to different ports.

# Resolved problems in CMW520-R1112

## ZDD05003

- Symptom: The CLI does not respond.
- Condition: This symptom might occur when the switch is accessed through SNMPv3 using 3DES authentication.

## ZDD04990

- Symptom: The switch might automatically close the HTTPS service (TCP port 443), and the web interface of the switch cannot be accessed through HTTPS (or SSH login fails).
- Condition: This symptom might occur if the following conditions exist:
  - HTTPS is enabled on the switch.
  - Use HTTPS to access the web interface of the switch.

## ZDD04944

- Symptom: The switch reboots when it requests an IP address from a DHCP server.
- Condition: This symptom might occur if the following conditions exist:
  - The DHCP server assigns multiple DHCP options.
  - DHCP client debugging is enabled on the switch..

## ZDD04931

- Symptom: The switch enabled with the DHCP server reboots when a PC accesses it through Web.
- Condition: This symptom might occur if the following conditions exist:
  - DHCP option 3 or 6 is configured as a string of 255 ASCII characters on the DHCP server.
  - A PC accesses the DHCP server through Web.

## ZDD04865

- Symptom: The switch reboots when an SSH user logs in.
- Condition: This symptom might occur if the free memory space of the switch is insufficient.

## ZDD04706

- Symptom: RADIUS authentication fails when the Vendor-Specific attribute sent by the RADIUS server is not in the standard TLV format.
- Condition: This symptom might occur when the Vendor-Specific attribute sent by the RADIUS server is not in the standard TLV format.

## LSD69613

- Symptom: The device information on the **Summary > Device Information** web page does not show port states.
- Condition: None.

## LSD69165

- Symptom: The GMT offset for Caracas is wrong on the **Device > System Time** time zone web page .
- Condition: None.

## LSD47115

- Symptom: An error message might appear during an operation on the **PoE > PoE >Port Setup** web page.
- Condition: None.

# Resolved problems in CMW520-R1111P02

## LSD071600

- Symptom: A 1G port repeatedly goes up and down.
- Condition: This symptom might occur when a 1G port is connected to a device that uses an RealTek RTL8169 chip.

# Resolved problems in CMW520-R1111P01

None

# Resolved problems in CMW520-R1111

## LSD65011

- Symptom: Garbled characters appear on the **Network > LLDP > Neighbor Summary** web page.
- Condition: This symptom exists in the **Network > LLDP > Neighbor Summary** Web page.

## LSD64981

- Symptom: A newly configured gateway might not overwrite the previous one when the gateway is configured multiple times through the **Wizard** web page.
- Condition: This symptom might occur when the gateway is configured multiple times through the **Wizard** web page.

## LSD47162

- Symptom: IMC might not display an error message when QoS application on IMC fails.
- Condition: This symptom might occur when QoS application on IMC fails.

## LSD50868

- Symptom: The **Network > IGMP Snooping** Web page is not easy to use due to lack of operation help information.
- Condition: This symptom exists in the **Network > IGMP Snooping** Web page.

## LSD50752

- Symptom: 10K-long packets cannot be forwarded between two ports on a V1910-48G switch.
- Condition: This symptom might occur when the port number of one port is between 1 and 24 and that of the other is between 25 and 48.

## LSD64667

- Symptom: The CLI of the switch might not respond after an NMS running SNMPTest connects to the switch as an SNMPv3 user using the SHA-3DES encryption algorithm.

- Condition: This symptom might occur when the SNMPv3 user account uses the SHA-3DES encryption algorithm and the NMS runs SNMPTest to connect to the switch.

#### ZDD04517

- Symptom: A DISMAN-PING-MIB::pingResultsOperStatus access failure occurs and the switch cannot recover from the failure and reboots occasionally.
- Condition: This symptom might occur when NQA operations continuously and quickly get or set the RPINGMib.

#### ZDD04543

- Symptom: The switch running LLDP reboots when the **display lldp neighbor-information** command is executed.
- Condition: This symptom might occur if the **display lldp neighbor-information** command is executed after the switch receives an LLDP packet in which the LCI length in the location ID TLV is 0.

#### ZDD04556

- Symptom: The switch running LLDP reboots when the **display lldp neighbor-information** command is executed.
- Condition: This symptom might occur if the **display lldp neighbor-information** command is executed after the switch receives an LLDP packet that has an organization-unknown TLV larger than 500 bytes.

#### ZDD04569

- Symptom: The switch reboots when receiving large amounts of traffic.
- Condition: This symptom might occur when the **debugging vty negotiate** command is enabled.

#### ZDD04596

- Symptom: The switch might reboot when it has large amounts of FTP traffic to process.
- Condition: None.

#### LSD67635

- Symptom: Walking MIB node entPhysicalHardwareRev.15 returns an incorrect value.
- Condition: This symptom might occur during a walk on MIB node entPhysicalHardwareRev.15.

## Resolved problems in CMW520-R1109

#### LSD63498

- Symptom: The gateway IP address could not be set in the web wizard.
- Condition: This symptom exists in the Web wizard.

#### LSD63499

- Symptom: The SSH service and HTTPS service are automatically enabled when the switch starts up (see the **Web > Network > Service** page), making key or PKI certificate key unable to be generated automatically.
- Condition: None.



### LSD61667

- Symptom: The file list on the web page might contain an “.XML” file.
- Condition: None.

### ZDD04165

- Symptom: The value of the Chassis ID field in the LLDP log information is garbled characters.
- Condition: This symptom might occur when the switch is connected to a Cisco IP phone and LLDP is enabled.

### ZDD04178

- Symptom: The source MAC-based ARP attack detection function could not detect and protect the switch against ARP attacks from fixed MAC addresses. and might affect the normal ARP learning function.
- Condition: This symptom might occur when the attack sources reside on a different network segment than the interface.

### ZDD04254

- Symptom: The FTP data session could not be established.
- Condition: This symptom might occur when the switch is used as the FTP client and the prompt of the FTP server is not that given in the RFC document.

## Resolved problems in CMW520-R1108P01

### LSD63812

- Symptom: The SFP ports are always down at the Link layer or the port statistics show the number of erroneous input packets constantly increase.
- Condition: This symptom might occur when the settings for the speed and duplex working mode parameters are both auto-negotiation.

## Resolved problems in CMW520-R1108

- This is the first release version.

## Related documentation

### Documentation set

- *Read This First (5998-1520) 6P101*
- *HP Small Biz Feedback (5998-2984)-6P100*
- *HP 1910-8G Switch Series Compliance and Safety Manual-5PW101*
- *HP V1910 Switch Series Compliance and Safety Manual-5PW100*
- *HP 1910 Switch Series Getting Started Guide-6W101*
- *HP 1910 Switch Series User Guide-Release 1511-6W100*

# Obtaining documentation

To find related documents, browse to the Manuals page of the HP Business Support Center website:

<http://www.hp.com/support/manuals>

# Contacting HP

For worldwide technical support information, see the HP support website:

<http://www.hp.com/support>

Before contacting HP, collect the following information:

- Product model names and numbers
- Technical support registration number (if applicable)
- Product serial numbers
- Error messages
- Operating system type and revision level
- Detailed questions

# Subscription service

HP recommends that you register your product at the Subscriber's Choice for Business website:

<http://www.hp.com/go/wwalerts>

After registering, you will receive email notification of product enhancements, new driver versions, firmware updates, and other product resources.

# Appendix A Feature list

## Hardware features

**Table 5 1910 series hardware features**

Item	Description
Physical dimensions (H × W × D)	43.6 × 440 × 160 mm (1.72 × 17.32 × 6.30 in.) (1910-16G)
	43.6 × 440 × 160 mm (1.72 × 17.32 × 6.30 in.) (1910-24G)
	43.6 × 440 × 260 mm (1.72 × 17.32 × 10.24 in.) (1910-48G)
	43.6 × 440 × 420 mm (1.72 × 17.32 × 16.54 in.) (1910-24G-PoE (170W))
	43.6 × 440 × 420 mm (1.72 × 17.32 × 16.54 in.) (1910-24G-PoE (365W))
	43.6 × 210 × 210 mm (1.72 × 8.27 × 8.27 in.) (1910-8G)
	43.6 × 300 × 260 mm (1.72 × 11.81 × 10.24 in.) (1910-8G-PoE+ (65W))
Weight	43.6 × 300 × 260 mm (1.72 × 11.81 × 10.24 in.) (1910-8G-PoE+ (180W))
	≤ 3 kg (6.61 lb) (1910-16G)
	≤ 3 kg (6.61 lb) (1910-24G)
	≤ 5 kg (11.02 lb) (1910-48G)
	≤ 6 kg (13.22 lb) (1910-24G-PoE (170W))
	≤ 7 kg (15.43 lb) (1910-24G-PoE (365W))
	≤ 2 kg (4.406 lb) (1910-8G)
≤ 3 kg (6.61 lb) (1910-8G-PoE+ (65W))	
≤ 3 kg (6.01 lb) (1910-8G-PoE+ (180W))	
Console port	1
Service ports	16 × 10/100/1000Base-T autosensing Ethernet ports + 4 GE SFP interfaces (1910-16G)
	24 × 10/100/1000Base-T autosensing Ethernet ports + 4 GE SFP interfaces (1910-24G)
	48 × 10/100/1000Base-T autosensing Ethernet ports + 4 GE SFP interfaces (1910-48G)
	24 × 10/100/1000Base-T autosensing Ethernet ports + 4 GE SFP interfaces (1910-24G-PoE (170W))
	24 × 10/100/1000Base-T autosensing Ethernet ports + 4 GE SFP interfaces (1910-24G-PoE (365W))
	8 × 10/100/1000Base-T autosensing Ethernet ports + 1 GE SFP interfaces (1910-8G)
	8 × 10/100/1000Base-T autosensing Ethernet ports + 1 GE SFP interfaces (1910-8G-PoE+ (65W))
8 × 10/100/1000Base-T autosensing Ethernet ports + 1 GE SFP interfaces (1910-8G-PoE+ (180W))	

Input voltage	<p>AC:  Rated voltage range: 100 VAC to 240 VAC, 50 Hz or 60 Hz  Maximum voltage range: 90 VAC to 264 VAC, 47 Hz or 63 Hz</p> <p>DC:  Use the external RPS unit provided by HP only, with the rated voltage ranging from -52 VDC to -55 VDC  Only 1910-24G-PoE (365W) supports RPS DC input</p>
Power consumption (full configuration)	<p>25.1 W (1910-16G)  31.5 W (1910-24G)  59.8 W (1910-48G)  255 W (85 W for system power consumption and 170 W for PoE power consumption) (1910-24G-PoE (170W))</p> <p>AC power input: 528 W (158 W for system power consumption and 370 W for PoE power consumption) (1910-24G-PoE (365W))  DC power input: 832 W (92 W for system power consumption and 740 W for PoE power consumption) (1910-24G-PoE (365W))</p> <p>14.4 W (1910-8G)  95W (1910-8G-PoE+ (65W))  230W (1910-8G-PoE+ (180W))</p>
Operating temperature	0°C to 45°C (32°F to 113°F)
Operating humidity (noncondensing)	10% to 90%

## Software features

**Table 6 Software features of the V1910 series**

Category	Features
Link aggregation	<p>Dynamic aggregation of Gigabit Ethernet (GE) ports  Dynamic link aggregation through Link Aggregation Control Protocol (LACP)  Manual link aggregation  Supports up to (total number of ports/2) link aggregation groups, each supporting up to eight GEs</p>
Flow control	IEEE 802.3x flow control and back pressure
Jumbo Frame	Maximum frame size of 10 KB
MAC address table	<p>8K MAC addresses  1K static MAC addresses  Blackhole MAC addresses  MAC address learning limit on a port</p>

<b>Category</b>	<b>Features</b>
VLAN	Port-based VLANs (256 VLANs) Voice VLAN
ARP	256 entries 64 static entries
VLAN virtual interface	8
IP Unicast route	Support IPv4 / IPv6 static route
Multicast	IGMP Snooping MLD Snooping
DHCP	DHCP client DHCP snooping DHCP relay agent
Broadcast/multicast/unicast storm control	Storm control based on port rate percentage PPS-based storm control bps-based storm control
MSTP	STP/RSTP/MSTP protocol Up to four spanning tree instances STP root protection BPDU protection
QoS/ACL	802.1p/DSCP precedence marking Four queues per port SP, WRR, and SP+WRR queue scheduling algorithms Port-based rate limit, with a minimum granularity of 64-kbps Flow-based traffic redirecting Time ranges Support IPv6 ACL
Mirroring	Port mirroring
Security features	Hierarchical management and password protection of users AAA authentication RADIUS authentication Port isolation 802.1X Portal
802.1X	Up to 1024 users Port-based and MAC address-based authentication Guest VLAN
Loading and upgrade	Loading and upgrade through XModem protocol Loading and upgrade through trivial file transfer protocol (TFTP)
Management	Simple Network Management Protocol (SNMP) Remote Monitoring (RMON) alarm, event and history recording

Category	Features
	DM NMS Web NMS System log Hierarchical alarms Stacking management NTP Power, fan, and temperature alarms pingv6 tracertv6
Maintenance	Debugging information output ping and tracert Virtual cable test

# Appendix B Upgrading software

You can upgrade software from Boot ROM menus or the CLI.

**Table 7 Approaches to loading software on the switch**

Approach	Section
Upgrading from Boot ROM menus	<a href="#">Loading Software Using XMODEM through Console Port</a>
	<a href="#">Loading Software Using TFTP through Ethernet Port</a>
	<a href="#">Loading Software Using FTP through Ethernet Port</a>
Upgrading from the CLI	<a href="#">Upgrading at the CLI</a>

Software images include the system software image and the Boot ROM image. They are packaged in a .bin file. You can download this file to upgrade both Boot ROM and system software, or upgrade only Boot ROM.

The Boot ROM image in the .bin package file consists of a basic segment and an extended segment. The basic segment is the minimum boot image. The extended segment enables the Boot ROM to bootstrap the system and upgrade system software.

**!** **IMPORTANT:**

When upgrading Boot ROM, upgrade both segments to ensure the functionality of the entire system.

## Upgrading software from Boot ROM menus

The Boot ROM menus include a basic Boot menu and an extended Boot menu.

The basic Boot menu is provided by the basic Boot ROM segment. From this menu, you can upgrade Boot ROM and run the extended Boot ROM. For more information, see "[Accessing the basic Boot menu.](#)"

The extended Boot menu is provided by the extended Boot ROM segment. From this menu, you can perform various tasks, including upgrading Boot ROM, upgrading and managing system software images, and managing files. For more information, see "[Accessing the extended Boot menu.](#)"

Both the basic Boot menu and extended Boot menu support using XMODEM to upgrade Boot ROM through the console port.

If the extended Boot ROM segment has corrupted, you can repair or upgrade it from the basic Boot menu.

---

**NOTE:**

The procedures for upgrading Boot ROM and system software from the extended Boot menu are the same except that you must choose different options from the Boot menu (**1** for upgrading system software, and **6** for upgrading Boot ROM) to start the upgrade procedure. This appendix describes only the Boot ROM upgrade procedure.

---

To upgrade software from Boot ROM menus:

1. Connect a configuration terminal such as a PC to the console port of the switch with a console cable.
2. Run the terminal emulation program on the PC.
3. Power on the switch.

The switch starts up and displays the following message:

```
Starting.....
Press Ctrl+D to access BASIC BOOT MENU
Press Ctrl+T to start memory test

*****
*
*          HP 1910-8G-PoE+ (65W) Switch BOOTROM, Version 160          *
*
*****
Copyright (c) 2010-2012 Hewlett-Packard Development Company, L.P.

Creation Date       : Dec 21 2012
CPU L1 Cache       : 32KB
CPU Clock Speed    : 333MHz
Memory Size        : 128MB
Flash Size         : 128MB
CPLD Version       : 001
PCB Version        : Ver.A
Mac Address        : 000EFB000020

Press Ctrl-B to enter Extended Boot menu...1
```

4. Press one of the shortcut key combinations at prompt.

**Table 8 Shortcut keys**

Shortcut keys	Prompt message	Function	Remarks
Ctrl+B	Press Ctrl-B to enter Extended Boot menu...	Accesses the extended Boot menu.	Press the keys within 1 second (in fast startup mode) or 5 seconds (in full startup mode) after the message appears. You can upgrade and manage system software and Boot ROM from this menu.



Ctrl+D	Press Ctrl+D to access BASIC BOOT MENU	Accesses the basic Boot menu.	Press the keys within 4 seconds after the message appears. You can upgrade Boot ROM or access the extended Boot ROM segment from this menu.
Ctrl+T	Press Ctrl+T to start memory test	Performs a RAM self-test.	Press the keys within 4 seconds after the message appears. Alternatively, you can choose option <b>1</b> from the BASIC-ASSISTANT menu to perform the task.

## Accessing the basic Boot menu

To access the basic Boot menu:

1. Press **Ctrl+D** within 4 seconds after the "Press Ctrl+D to access BASIC BOOT MENU" prompt message appears. If you fail to do this within the time limit, the system starts to run the extended Boot ROM segment.

```
*****
*
*          BASIC BOOTROM, Version 160
*
*****

      BASIC BOOT MENU

1. Update full BootRom
2. Update extended BootRom
3. Update basic BootRom
4. Boot extended BootRom
0. Reboot
Ctrl+U: Access BASIC-ASSISTANT MENU

Enter your choice(0-4):
```

**Table 9 Basic Boot ROM menu options**

Option	Task
1. Update full BootRom	Update the entire Boot ROM, including the basic segment and the extended segment. To do so, you must use XMODEM and the console port. For more information, see <a href="#">Loading Software Using XMODEM through Console Port</a> .

Option	Task
2. Update extended BootRom	Update the extended Boot ROM segment. To do so, you must use XMODEM and the console port. For more information, see <a href="#">Loading Software Using XMODEM through Console Port</a> .
3. Update basic BootRom	Update the basic Boot ROM segment. To do so, you must use XMODEM and the console port. For more information, see <a href="#">Loading Software Using XMODEM through Console Port</a> .
4. Boot extended BootRom	Access the extended Boot ROM segment. For more information, see <a href="#">Accessing the extended Boot menu</a> .
0. Reboot	Reboot the switch.
Ctrl+U: Access BASIC-ASSISTANT MENU	Press <b>Ctrl + U</b> to access the BASIC-ASSISTANT menu (see <a href="#">Table 11</a> ).

**Table 10 BASIC-ASSISTANT menu options**

Option	Task
1. RAM Test	Perform a RAM self-test.
2. Reserved	Reserved option field.
3. Reserved	Reserved option field.
0. Return to boot menu	Return to the basic Boot menu.

## Accessing the extended Boot menu

To access the extended Boot menu:

1. Press **Ctrl+B** within 1 second (in fast startup mode) or 5 seconds (in full startup mode) after the "Press Ctrl-B to enter Extended Boot menu..." prompt message appears. If you fail to do this, the system starts decompressing the system software.

BootRom password: Not required. Please press Enter to continue.

Alternatively, you can enter **4** in the basic Boot menu to access the extended Boot menu.

2. Press **Enter** at the prompt for password.

The "Password recovery capability is enabled." or "Password recovery capability is disabled." message appears, followed by the extended Boot menu. Availability of some menu options depends on the state of password recovery capability (see [Table 11](#)).

Password recovery capability is enabled.

BOOT MENU

1. Download application file to flash
2. Select application file to boot
3. Display all files in flash
4. Delete file from flash
5. Restore to factory default configuration

6. Enter BootRom upgrade menu  
 7. Skip current system configuration  
 8. Reserved  
 9. Set switch startup mode  
 0. Reboot  
 Ctrl+F: Format File System  
 Ctrl+P: Skip Super Password  
 Ctrl+R: Download application to SDRAM and Run  
 Ctrl+Z: Access EXTEND-ASSISTANT MENU

Enter your choice(0-9):

**Table 11 Extended Boot ROM menu options**

Option	Tasks
1. Download application file to flash	Download a .bin software package file to the flash. If password recovery capability is enabled, you can use any version of the system software image for upgrade. If password recovery capability is disabled, you can use only the Release 1513P07 version (or higher) for upgrade.
2. Select application file to boot	Specify the main and backup system software images for the next startup: <ul style="list-style-type: none"> <li>• If password recovery capability is enabled, you can specify a system software image of any version.</li> <li>• If password recovery capability is disabled, the system software image version must be R1513P07 or higher.</li> </ul>
3. Display all files in flash	Display files on the flash.
4. Delete file from flash	Delete files to free storage space.
5. Restore to factory default configuration	Delete the current next-startup configuration files and restore the factory-default configuration. This option is available only if password recovery capability is disabled.
6. Enter BootRom upgrade menu	Access the Boot ROM upgrade menu. If password recovery capability is enabled, you can upgrade the Boot ROM to any version. If password recovery capability is disabled, you can upgrade the Boot ROM to only Version 160 or higher.
7. Skip current system configuration	Start the switch without loading any configuration file. This is a one-time operation and takes effect only for the first system boot or reboot after you choose this option. This option is available only if password recovery capability is enabled.
8. Reserved	Reserved option field.
9. Set switch startup mode	Set the startup mode to fast startup mode or full startup mode.
0. Reboot	Reboot the switch.
Ctrl+F: Format File System	Format the current storage medium.

Option	Tasks
Ctrl+P: Skip Super Password	<p>Load the next-startup configuration file with all user privilege passwords configured with the <b>super password</b> command ignored.</p> <p>This is a one-time operation and takes effect only for the first system boot or reboot after you choose this option.</p> <p>This option is available only if password recovery capability is enabled.</p>
Ctrl+R: Download application to SDRAM and Run	<p>Download a system software image and start the switch with the image.</p> <p>This option is available only if password recovery capability is enabled.</p>
Ctrl+Z: Access EXTEND-ASSISTANT MENU	<p>Access the EXTEND-ASSISTANT menu.</p> <p>For options in the menu, see <a href="#">Table 12</a>.</p>

**Table 12 EXTEND-ASSISTANT menu options**

Option	Task
1. Display Memory	Display data in the memory.
2. Search Memory	Search the memory for a specific data segment.
0. Return to boot menu	Return to the extended Boot ROM menu.

## Loading Software Using XMODEM through Console Port

You can connect a PC or terminal to the console port to download files to the switch by using XMODEM. XMODEM supports 128-byte data packets and provides the reliability mechanisms including checksum, CRC, and retransmissions (up to 10).

### Setting terminal parameters

Run a terminal emulator program on the console terminal, for example, a PC.


The following are the required terminal settings:

- Bits per second—38,400
- Data bits—8
- Parity—None
- Stop bits—1
- Flow control—None
- Emulation—VT100

Follow these steps to set terminal parameters, for example, on a Windows XP HyperTerminal:

- Step 1** Select **Start > All Programs > Accessories > Communications > HyperTerminal**, and in the **Connection Description** dialog box that appears, type the name of the new connection in the **Name** text box and click **OK**.

**Figure 1** Connection description of the HyperTerminal




**Step2** Select the serial port to be used from the **Connect using** drop-down list, and click **OK**.

**Figure 2** Set the serial port used by the HyperTerminal connection




**Step3** Set **Bits per second** to **38400**, **Data bits** to **8**, **Parity** to **None**, **Stop bits** to **1**, and **Flow control** to **None**, and click **OK**.

Figure 3 Set the serial port parameters




**Step4** Select **File > Properties** in the HyperTerminal window.

Figure 4 HyperTerminal window



**Step5** Click the **Settings** tab, set the emulation to **VT100**, and click **OK** in the **Switch Properties** dialog box.

Figure 5 Set terminal emulation in Switch Properties dialog box



## Upgrading Boot ROM

Perform the following tasks to upgrade Boot ROM by using XMODEM through the console port:

**1.** Access the Boot menu, and enter **6** or press **Ctrl + U** to enter the Boot ROM update menu:

1. Update full BootRom
2. Update extended BootRom
3. Update basic BootRom
0. Return to boot menu

Enter your choice(0-3):

---

**!** **IMPORTANT:**

Always select option **1** to upgrade the entire Boot ROM. You can use option **2** or option **3** only under the guidance of an HP engineer.

---

**2.** Enter **1** at the Boot ROM update menu to set the protocol parameters.

1. Set TFTP protocol parameter
2. Set FTP protocol parameter
3. Set XMODEM protocol parameter
0. Return to boot menu

Enter your choice(0-3):

**3.** Enter **3** to set the XMODEM download baud rate.



Please select your download baudrate:

1. 9600
2. 19200
3. \*38400
4. 57600
5. 115200
0. Return

Enter your choice (0-5):

**4.** Select an appropriate download rate, for example, enter **5** to select 115200 bps.

Download baudrate is 115200 bps


Please change the terminal's baudrate to 115200 bps and select XMODEM protocol

Press enter key when ready

**5.** Set the serial port on the terminal to use the same baud rate and protocol as the console port. If you select 38400 bps as the download rate for the console port, skip this task.


**Step1** Select **Call > Disconnect** in the HyperTerminal window to disconnect the terminal from the switch.

**Figure 6 Disconnect the terminal from the switch**




**Step2** Select **File > Properties**. In the **Properties** dialog box, click **Configure** (see [Figure 7](#) ), and then select **115200** from the **Bits per second** drop-down list box (see [Figure 8](#) ).

Figure 7 Properties dialog box




**Figure 8 Modify the baud rate**



**Step3** Select **Call > Call** to reestablish the connection.

**Figure 9 Reestablish the connection**



---

**NOTE:**

The new settings can take effect only after you reestablish the connection.

---

6. Upload the software package file from the terminal to the switch.

**Step4** After establishing a connection between the terminal and the switch, press **Enter** in the HyperTerminal window.


Now please start transfer file with XMODEM protocol.

If you want to exit, Press <Ctrl+X>.


Loading ...CCCCCCCCCC

**Step5** Select **Transfer > Send File** in the HyperTerminal window (see [Figure 10](#)), and click **Browse** in the pop-up dialog box (see [Figure 11](#)) to select the source file (for example, **update.bin**), and select **Xmodem** from the **Protocol** drop-down list.

**Figure 10 Transfer menu**




**Figure 11 File transmission dialog box**



**Step6** Click **Send**. The following dialog box appears:

**Figure 12 Send the application file using XMODEM**



**7.** Upgrade Boot ROM on the switch.

When the terminal displays the following prompt, enter **Y** to update the basic Boot ROM section:

```
Loading ...CCCC Done!  
Will you Update Basic BootRom? (Y/N):Y
```

When the terminal displays the following prompt, enter **Y** to update the extended Boot ROM section:

```
Updating Basic BootRom.....Done!  
Updating extended BootRom? (Y/N):Y
```

When the Boot ROM upgrade is completed, the terminal displays the following information:

```
Updating extended BootRom.....Done!  
Please change the terminal's baudrate to 38400 bps, press ENTER when ready.
```

8. If you are using a download rate other than 38400 bps, restore the baud rate of the serial port on the terminal to 38400 bps. If the baud rate is 38400 bps, skip this step.
9. Press any key to return to the Boot ROM update menu and enter **0**. On the Boot menu that appears, enter **0** to restart the switch so the updated image can take effect. The following is the Boot ROM update menu:
  1. Update full BootRom
  2. Update extended BootRom
  3. Update basic BootRom
  0. Return to boot menuEnter your choice(0-3):

## Upgrading system software

To upgrade system software, enter **1** at the Boot menu, and the following menu appears:

```
1. Set TFTP protocol parameter  
2. Set FTP protocol parameter  
3. Set XMODEM protocol parameter  
0. Return to boot menu  
Enter your choice(0-3):
```

Enter **3** to set the XMODEM parameters for downloading the software package file.

The subsequent procedure is the same as loading Boot ROM images, except that you must set the attribute of the file as **main**, **backup**, or **none** to complete the file loading.

```
Writing flash.....  
.....Done!  
Please input the file attribute (Main/Backup/None) M  
Done!
```

---

### NOTE:

- The switch always attempts to boot first with the main file, and if the attempt fails for example, because the main file is not available, the switch tries to boot with the backup file. A file with the **none** attribute is just stored in Flash memory for backup and you must change its attribute to make it usable at reboot.
  - If a file with the same attribute as the file you are loading is already in the Flash memory, the attribute of the old file changes to **none** after the new file becomes valid.
  - The switch automatically updates Boot ROM when loading system software.
- 

## Loading Software Using TFTP through Ethernet Port

The switch can work as a TFTP client to download files from a TFTP server.

## Upgrading Boot ROM

1. Connect an Ethernet port of the switch to the server and connect the console port of the switch to a PC

---

### NOTE:

- The PC and the TFTP/FTP server can be co-located.
  - The HP V1910 Switch Series do not come with any TFTP server program, and you must install one yourself.
- 

2. Run the TFTP server program on the server and specify the source file path.
3. Run a terminal emulator program on the PC, power on the switch, access the Boot menu, and enter **6** to access the following Boot ROM update menu:

1. Update full BootRom
2. Update extended BootRom
3. Update basic BootRom
0. Return to boot menu

Enter your choice(0-3):

4. Enter **1** to upgrade the entire Boot ROM and access the following protocol parameter setting menu:

Bootrom update menu:

1. Set TFTP protocol parameter
2. Set FTP protocol parameter
3. Set XMODEM protocol parameter
0. Return to boot menu

Enter your choice(0-3):

5. Enter **1** to set the TFTP parameters.

```
Load File Name      :update.bin
Server IP Address   :10.10.10.2
Local IP Address    :10.10.10.3
Gateway IP Address :
```

**Table 13 Description of the TFTP parameters**

Item	Description
Load File Name :	Name of the file to be downloaded (for example, <b>update.bin</b> )
Server IP Address :	IP address of the TFTP server (for example, 10.10.10.2)
Local IP Address :	IP address of the switch (for example, 10.10.10.3)
Gateway IP Address :	IP address of the gateway (in this example, no gateway is required because the server and the switch are on the same subnet)

---

### NOTE:

If the switch and the server are on different subnets, you must specify a gateway address for the switch.

---

6. Enter all required parameters.

```
Loading.....  
.....  
.....Done!  
Will you Update Basic BootRom? (Y/N):Y
```

Enter **Y** at the prompt to upgrade the basic Boot ROM section.

```
Updating Basic BootRom.....Done!  
Updating extended BootRom? (Y/N):Y
```

Enter **Y** at the prompt to upgrade the extended Boot ROM section.

When the upgrade is completed, the following information appears:

```
Updating extended BootRom.....Done!
```

7. Press any key to return to the Boot ROM update menu, enter **0** to return to the Boot menu, and enter **0** to restart the switch from the Boot menu so the upgraded Boot ROM can take effect.

```
Press enter key when ready  
1. Update full BootRom  
2. Update extended BootRom  
3. Update basic BootRom  
0. Return to boot menu  
Enter your choice(0-3):
```

## Upgrading system software

To upgrade switch software, enter **1** at the Boot menu to access the following menu:

```
1. Set TFTP protocol parameter  
2. Set FTP protocol parameter  
3. Set XMODEM protocol parameter  
0. Return to boot menu  
Enter your choice(0-3):
```

Enter **1** to set the TFTP parameters.

The subsequent procedure of is the same as upgrading Boot ROM, except that you must set the attribute of the file as **main**, **backup**, or **none** to complete the file loading.

```
Writing flash.....  
.....Done!  
Please input the file attribute (Main/Backup/None) M  
Done!
```

---

### NOTE:

- If a file with the same attribute as the file you are loading is already in the Flash memory, the attribute of the old file changes to **none** after the new file becomes valid.
  - The switch automatically updates Boot ROM when loading system software.
-

# Loading Software Using FTP through Ethernet Port

The switch can work as an FTP server or FTP client to download files through an Ethernet port. This section uses the switch as an FTP client to describe the procedure.

## Upgrading Boot ROM

---

### NOTE:

When upgrading Boot ROM, the switch can work only as an FTP client.

---

1. Connect an Ethernet port of the switch to the server and connect the console port of the switch to a PC.
2. Run an FTP server program on the server, configure an FTP username and password, and specify the source file path.
3. Run a terminal emulator program on the PC, power on the switch, access the Boot menu, and enter **6** to access the following Boot ROM update menu:

```
1. Update full BootRom
2. Update extended BootRom
3. Update basic BootRom
0. Return to boot menu
```

Enter your choice(0-3):

4. Enter **1** to upgrade the entire Boot ROM and access the following protocol parameter setting menu:

Bootrom update menu:

```
1. Set TFTP protocol parameter
2. Set FTP protocol parameter
3. Set XMODEM protocol parameter
0. Return to boot menu
```

Enter your choice(0-3):

5. Enter **2** to set the FTP parameters.

```
Load File Name      :update.bin
Server IP Address   :10.10.10.2
Local IP Address    :10.10.10.3
Gateway IP Address  :0.0.0.0
FTP User Name       :V1910
FTP User Password   :V1910
```

**Table 14 Description of the FTP parameters**

Item	Description
Load File Name :	Name of the file to be downloaded (for example, <b>update.bin</b> )
Server IP Address :	IP address of the FTP server (for example, 10.10.10.2)
Local IP Address :	IP address of the switch (for example, 10.10.10.3)



Item	Description
Gateway IP Address :	IP address of the gateway (in this example, no gateway is required because the server and the switch are on the same subnet)
FTP User Name	Username for accessing the FTP server, which must be the same as configured on the FTP server.
FTP User Password	Password for accessing the FTP server, which must be the same as configured on the FTP server.

**NOTE:**

If the switch and the server are on different subnets, you must specify a gateway address for the switch.

**6.** Enter all required parameters.

Will you Update Basic BootRom? (Y/N):Y

Enter **Y** at the prompt to upgrade the basic Boot ROM section.

Updating Basic BootRom.....Done!

Updating extended BootRom? (Y/N):Y

Enter **Y** at the prompt to upgrade the extended Boot ROM section.

When the upgrade is completed, the following information appears:

Updating extended BootRom.....Done!

**7.** Press any key to return to the Boot ROM update menu, enter **0** to return to the Boot menu, and enter **0** to restart the switch from the Boot menu so the upgraded Boot ROM can take effect.

Press enter key when ready

- 1. Update full BootRom
- 2. Update extended BootRom
- 3. Update basic BootRom
- 0. Return to boot menu

Enter your choice(0-3):

## Upgrading system software

To upgrade switch software, enter **1** in the Boot menu to access the following menu:

- 1. Set TFTP protocol parameter
- 2. Set FTP protocol parameter
- 3. Set XMODEM protocol parameter
- 0. Return to boot menu

Enter your choice(0-3):

Enter **2** to set the FTP parameters.

The subsequent procedure is the same as upgrading Boot ROM, except that you must set the attribute of the file as **main**, **backup**, or **none** to complete the file loading.

Writing flash.....

.....Done!

Please input the file attribute (Main/Backup/None) M

Done!

---

**NOTE:**

- If a file with the same attribute as the file you are loading is already in the Flash memory, the attribute of the old file changes to **none** after the new file becomes valid.
  - The switch automatically updates Boot ROM when loading system software.
- 

## Upgrading at the CLI

### Loading Software Using TFTP

You can remotely download Boot ROM and system software images from a TFTP server at the CLI as follows.

Step 1: Configure an IP address for the switch

```
<HP V1910 Switch>ipsetup ip-address 192.168.1.2 24
```

Step 2: Download the system software image file from the TFTP server.

```
<HP V1910 Switch>upgrade 192.168.1.1 update.bin runtime
The file flash:/ main.bin exists. Overwrite it? [Y/N]:y
  Verifying server file...
  Deleting the old file, please wait...
```

```
File will be transferred in binary mode
Downloading file from remote TFTP server, please wait.../
TFTP: 10262272 bytes received in 104 second(s)
File downloaded successfully.
```

The specified file will be used as the boot file at the next reboot.

Step 3: Download and load the Boot ROM file.

```
<HP V1910 Switch>upgrade 192.168.1.1 update.btm bootrom
```

```
File will be transferred in binary mode
Downloading file from remote TFTP server, please wait...|
TFTP: 259324 bytes received in 2 second(s)
File downloaded successfully.
  BootRom file updating finished!
```

Step 4: Reboot the device to validate the new system software.

```
<HP V1910 Switch> reboot
```

Note that if flash memory is insufficient, load the Boot ROM image first and delete useless files to free up Flash memory before you load the system software image.